

SECRET

OUT60/45

TOP SECRET 192021Z CITE [REDACTED]

2509

1966 OCT 19 20 25Z

25X1

25X1

1. [REDACTED] HAS BEEN EXPERIENCING CONSIDERABLE DIFFICULTY IN THE EFFECTIVE USE OF THE UNIVAC-1004 DATA LINK HIGH-SPEED COMMUNICATIONS SYSTEM. SOME HAS STEMMED FROM THE LACK OF FINITE AND PRECISE CONTROL AND OPERATING PROCEDURES AND OPERATIONAL DIFFICULTIES WHICH DO NOT BECOME APPARENT UNTIL THE DATA LINK IS ACTUALLY ACTIVATED.

25X1

2. THEREFORE, IN ORDER TO ALLEVIATE THESE OPERATIONAL PROBLEMS, SPEED UP TRANSMISSION TIME, AND AVOID DELAYS IN THE RECEIPT OF INFORMATION, IT IS PROPOSED THAT A MEETING BE HELD AT THE EARLIEST POSSIBLE TIME BETWEEN REPRESENTATIVES OF [REDACTED] TO FORMULATE DETAILED OPERATIONS PROCEDURES TO ENSURE "0" DEFECT TRANSMISSIONS BY REQUIRING DAILY TEST TRANSMISSIONS AT PRESCRIBED TIMES TO DETERMINE THE RELIABILITY OF THE DATA-LINK SYSTEM.

20 OCT 1966 25X1

3. YOUR ASSISTANCE IN THIS MATTER WILL BE GREATLY APPRECIATED. [REDACTED] IS PREPARED TO TABLE A DRAFT PROCEDURE IN ORDER TO KICK OFF A FRUITFUL EXCHANGE OF IDEAS TO STANDARDIZE OPERATIONS AND MINIMIZE EQUIPMENT DOWN TIME.

TOP SECRET

-END OF MESSAGE-

DISTRIBUTION		
Cy No.	Office	Action
1	File	
2	OS	
	SEC BR	
	TDS	
3	GSD	25X1-
4	IPD	
	PD	
	PSD	
	PSD-IGS	
9	TID	
	IAD	
	PAQ	
	DIAXX-4	
	SPAD	
	NSA-LO	
	DIA-AP	

Advance copy
Sanitized